



- Never stick a foot or any part of your body outside the operator area.
- Stop your forklift completely before getting off.
- Yield or stop for pedestrians.
- Use your horn when you come to a crosswalk or intersection.
- Travel in the direction that gives you the best view.
- Look where you are going before you change direction of travel.

